NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

These are the findings of an inspection of your facility on the date(s) indicated above:

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 6/14/23 2:15 pm

ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER 2976 COUNTY RD 48 CANANDAIGUA NY 14424 Inspector #: 72

1. Shelter is structurally sound	Yes	
2. Housing area and equipment is sanitized regularly		
3. Repairs are done when necessary		
See remarks.		
4. Dogs are handled safely	Yes	
5. Adequate space is available for all dogs	Yes	
6. Light is sufficient for observation	Yes	
7. Ventilation is adequate	Yes	
8. Drainage is adequate	Yes	
9. Temperature extremes are avoided		
10. Clean food and water is available and in ample amount		
11. Veterinary care is provided when necessary		
12. Dogs are euthanized humanely, by authorized personnel		
13. Complete intake and disposition records are maintained for all seized dogs	Yes	
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes	
15. Redemption period is observed before adoption, euthanasia or transfer	Yes	
16. Owners of identified dogs are properly notified	Yes	
17. Redeemed dogs are licensed before release	Yes	
18. Proper impoundment fees paid before dogs are released	Yes	
19. Written contract or lease with municipality	Yes	

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

REMARKS:

Repairs:

The floor drains in kennels are completely rusted: Drain in kennel #14 rusted since last inspection. It has been re-coated with another method to test durability.

The cinder blocks in the kennel area are not sealed and porous. It is recommended that porous surfaces be sealed to prevent further water damage and allow for thorough sanitation. It would also allow for quicker drying times to alleviate extended damp conditions in the housing areas.

Kennels #2 and #8 have large amount of grout that is missing between cinder blocks and cannot be properly disinfected.

REPRESENTATIVE PRESENT FOR INSPECTION:

TITLE: Executive Director

WIlliam Martin

REVIEWED BY: Inspector #: 64
REVIEWED DATE: 06/26/2023