NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30** Purpose: **Inspection**

DATE/TOA: **11/20/20 10:45 am**

HUMANE SOCIETY OF WALDEN
2489 ALBANY POST ROAD
WALDEN NY 12586

Inspector #: **67**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	No
Exterior kennel runs on the "back side of the building", from entry door:- kennels 2 and 7 have gate cross bar fully rusted through with dogs contained. The concern is injury to the dogs' feet when jumping up at the gate.	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3304	Town of Crawford
4811	Town of Mamakating
3312	Town of Montgomery
3303	Town of Cornwall
5117	Town of Shawangunk
5119	Town of Wawarsing

REMARKS:

Many of the exterior kennel runs connected to the interior housing are in need of repair or re sealing, but were not in use at the time of inspection.

Please note the following repairs necessary before dogs are to utilize these runs.

Exterior runs on the "entry" side of the building, starting numerically from entry gate to runs - runs 1-5 require concrete cracks to filled and concrete floor resealed; runs 6-9 have "pitting" of the concrete that needs to be filled and resealed; runs 5 requires replacement of gate as cross bar support rusted through with sharp edges (safety concern); runs 9 & 10 have chain link fencing supports rusted and broken in need of replacing. (safety concern). Much of the chain link fencing is rusted and in need of attention.

Exterior kennel runs on the "back" side of the building, starting numerically from the entry gate to runs - kennel 1 has chain link support in need of repair; runs 2,3,4,&7 have rusted cross bar support in gates that require repair or replacement of gate; kennel 9 needs crack in concrete floor filled and resealed; kennel 11 requires concrete erosion of guillotine saddle to be repaired.

Interior "front cage" should have cover over floor drain opening to prevent dog from stepping in it; holes in walls need to be repaired - plaster exposing lathe and insulation behind and concrete holes where previous plumbing came through.

Any questions regarding these repairs can be directed to Inspector Amels 845-500-1498.

REPRESENTATIVE PRESENT FOR INSPECTION: **Lisa Rodriguez**
TITLE: **shelter staff**

REVIEWED BY: **Inspector #: 18**
REVIEWED DATE: **11/30/2020**