## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

Rating: Satisfactory182 Purpose: Inspection

DATE/TOA: 12/11/13 11:00 am

HORNBY SHELTER 5004 CTY. RTE. 42 Beaver Dams NY 14812 Inspector #: 809

These are the findings of an inspection of your facility on the date(s) indicated above:

## 1. Shelter is structurally sound

9. Temperature extremes are avoided

Yes

Yes

The walls in the outdoor kennels are starting to deteriorate creating some jagged edges near the bottom adjacent to the "dog doors". It is recommended that this be repaired in the near future.

2. Housing area and equipment is sanitized regularly
3. Repairs are done when necessary
4. Dogs are handled safely
5. Adequate space is available for all dogs
6. Light is sufficient for observation
7. Ventilation is adequate
8. Drainage is adequate
Yes

Although there are heat lamps in the kennels, the dog doors are not flush with the wall and cold air/wind can get inside. It is recommended that during very cold weather a guillotine like cover be put over the dog doors especially during the night.

10. Clean food and water is available and in ample amount

Yes

11. Veterinary care is provided when necessary Not Applicable

12. Dogs are euthanized humanely, by authorized personnelYes13. Complete intake and disposition records are maintained for all seized dogsYes

14. Dogs transferred for purposes of adoption in compliance with Article 7 Not Applicable

15. Redemption period is observed before adoption, euthanasia or transferYes16. Owners of identified dogs are properly notifiedYes17. Redeemed dogs are licensed before releaseYes18. Proper impoundment fees paid before dogs are releasedYes

19. Written contract or lease with municipality

Not Applicable

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME	
4616	Town of Hornby	

## **REMARKS**:

TITLE: shelter manager

The shelter is in good condition. It has been cleaned adequately since the last inspection. Some recommendations have been made to maintain the structural integrity of the kennel as well as to protect the dogs from cold wind blowing in through the dog doors. The specific recommendations are listed under the "deficiencies" section. It is anticipated that the shelter will be re-inspected six months from now.

REPRESENTATIVE PRESENT FOR INSPECTION:

**Kurtis Bickle** 

**REVIEWED BY:** 

REVIEWED DATE: 12/23/2013