NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 6/19/15 2:00 pm

MONTGOMERY COUNTY SPCA 1007 RT 5S AMSTERDAM NY 12010 Inspector #: 54
Inspector #: 50

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound

No

Eight outdoor runs at the rear of the kennel and eight outdoor runs at the front of the kennel building; the pipes that comprise the door frames that the chain link is attached to, are rusty, broken and have jagged edges at both corners at the bottom of the door, and the pipe that connects the corners at the bottom of the door are severely rusted. These areas pose a risk of injury to the dogs contained therein and cannot be effectively cleaned and disinfected.

2. Housing area and equipment is sanitized regularly

Yes

Yes

No

3. Repairs are done when necessary

No

Bolts sticking out from the concrete around the door openings in the outdoor runs need to be removed. Several areas in the concrete of the outdoor runs, where there are large cracks, chips and holes need to be filled in. Four outdoor freestanding kennels have several areas of loose and broken wire, and exposed sharp pipes (where patches have been attempted) that need repair. Three more outdoor freestanding kennels are now in use and have areas of loose wire.

Yes
Yes
Not Applicable
Yes

Contracts were still unavailable.

19. Written contract or lease with municipality

18. Proper impoundment fees paid before dogs are released

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
2704	Town of Florida
2701	Town of Amsterdam
4205	Town of Rotterdam
2711	City of Amsterdam
4204	Town of Princetown

REMARKS:

TITLE: Manager

N/A=handled by DCO's.

As previously reported, several areas of chain link wire that are rusty and pitted need resurfacing or replacement as they cannot be effectively cleaned and disinfected to prevent the spread of disease.

Changes or improvements to correct the deficiencies have not been attempted since the previous inspection on April 24, 2015.

REPRESENTATIVE PRESENT FOR INSPECTION:

Antonio Baker

REVIEWED BY: Inspector #: 50

REVIEWED DATE: 06/25/2015