

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory⁹¹**

Purpose: **Inspection**

DATE/TOA: **11/6/19 11:45 am**

**BUFFALO CITY SHELTER
 380 NORTH OAK STREET
 BUFFALO NY 14213**

Inspector #: **56**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | Yes |
| <i>SEE "REMARKS".</i> | |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Not Applicable |
| 12. Dogs are euthanized humanely, by authorized personnel | Not Applicable |
| 13. Complete intake and disposition records are maintained for all seized dogs | Not Applicable |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Not Applicable |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Not Applicable |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Not Applicable |
| 18. Proper impoundment fees paid before dogs are released | Not Applicable |
| 19. Written contract or lease with municipality | Not Applicable |

Town - City - Village Information for Inspection:

<u>TCV CODE</u>	<u>TCV NAME</u>
1426	City of Buffalo

REMARKS:

ONLY A PHYSICAL INSPECTION OF THE SHELTER WAS CONDUCTED. Items marked "Not Applicable" were not inspected.

REGARDING "Repairs are done when necessary":

The damaged wallboard and quarantine room door have both been repaired.

At the time of inspection, city workers were making repairs to the shelter's gas supply line. Heaters were brought in to maintain temperatures. The missing doorknob was shown to a worker who stated it would be repaired.

Director Kelly McCartney stated the roof still may leak as no repairs have been made since the previous inspection. Since progress has been made in other areas, the next inspection will be conducted in approximately three months.

REPRESENTATIVE PRESENT FOR INSPECTION: **Kelly McCartney**
TITLE: **Director**

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **12/03/2019**