

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory182**

Purpose: **Inspection**

DATE/TOA: **1/4/14 2:00 pm**

**CANISTEO MUNICIPAL SHELTER
67 DEPOT ST.
CANISTEO NY 14823**

Inspector #: **809**

These are the findings of an inspection of your facility on the date(s) indicated above:

- 1. Shelter is structurally sound** Yes
- 2. Housing area and equipment is sanitized regularly** No
There was an empty cage with a full food bowl still in place. No dogs were in the shelter during the unannounced inspection.
- 3. Repairs are done when necessary** Not Applicable
This is a brand new structure. No repairs have been necessary at this time.
- 4. Dogs are handled safely** Yes
- 5. Adequate space is available for all dogs** Yes
- 6. Light is sufficient for observation** Yes
- 7. Ventilation is adequate** Yes
- 8. Drainage is adequate** Yes
- 9. Temperature extremes are avoided** Yes
- 10. Clean food and water is available and in ample amount** Yes
- 11. Veterinary care is provided when necessary** Yes
- 12. Dogs are euthanized humanely, by authorized personnel** Yes
- 13. Complete intake and disposition records are maintained for all seized dogs** Yes
- 14. Dogs transferred for purposes of adoption in compliance with Article 7** Yes
- 15. Redemption period is observed before adoption, euthanasia or transfer** Yes
- 16. Owners of identified dogs are properly notified** Not Applicable
- 17. Redeemed dogs are licensed before release** Yes
- 18. Proper impoundment fees paid before dogs are released** Yes
- 19. Written contract or lease with municipality** Yes
This shelter contracts with the town of Hartsville for sheltering services.

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
4607	Town of Canisteo
4615	Town of Hartsville

REMARKS:

Dave Phillips and I did an unannounced inspection of the shelter on 1/2/14. There were no dogs in the shelter at the time of inspection on. A food bowl was full in an empty cage. There were some items left on the floor. General housekeeping needs to be improved. I met with Gary Hadsell on 1/4/14.

It is recommended that the rusted kennels be replaced or re-finished. The upper parts of the walls need to be finished so the insulation is not exposed inside the kennel. Ventilation was adequate at the time of the inspection, but may prove to be a challenge in the warmer months or when the shelter houses numerous dogs. Consideration should be given to installing a large exhaust fan at some future date. The drain from the sink allows water to run downhill to the drainage area. Consideration should be given to install a means for the water to drain directly into the drainage area.

REPRESENTATIVE PRESENT FOR INSPECTION: **Gary Hadsell**
TITLE: **Shelter manager**

REVIEWED BY:
REVIEWED DATE: **01/09/2014**