## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

Rating: Satisfactory60 Purpose: Inspection

DATE/TOA: 3/30/17 11:00 am

HORNBY SHELTER 5004 CTY. RTE. 42 Beaver Dams NY 14812 Inspector #: 14

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Not Applicable
Handled by DCO	
15. Redemption period is observed before adoption, euthanasia or transfer	Not Applicable
Handled by DCO	
16. Owners of identified dogs are properly notified	Not Applicable
Handled by DCO	N. (A. P. 11
17. Redeemed dogs are licensed before release	Not Applicable
Handled by DCO	Not Applicable
18. Proper impoundment fees paid before dogs are released	Not Applicable
Handled by DCO  19. Written contract or lease with municipality	Not Applicable
10. Written contract of lease with municipality	1401 Applicable

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
4616	Town of Hornby

## REMARKS:

TITLE: n/a

Gained access to shelter with key provided by the town highway department.

Internal walls of kennel have been covered with four feet high panels of impervious material. Rusted areas of the outside kennel framework and chain link will be painted and or replaced in the near future. The last inspection report citing this issue was not received by the town until November, leaving no suitable weather conditions to complete the project. Next inspection will be conducted in sixty days to ascertain that rusted areas have been addressed.

REPRESENTATIVE PRESENT FOR INSPECTION:

n/a

REVIEWED BY: Inspector #: 833

REVIEWED DATE: **04/13/2017**