## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

Rating: Unsatisfactory30

Purpose: Inspection

DATE/TOA: 12/2/22 12:00 pm

Inspector #: 074

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	No
Exposed wood walls and raised wooden boxes, rusted metal baffle door gui floor cannot be properly cleaned and disinfected.	ides, and unsealed areas of concrete
3. Repairs are done when necessary	No
Aluminum plating behind chain link at back of kennels is bent/damaged cau dog. Wood along baffle door edges has been chewed.	ising sharp edges that could injure a
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Jeff Johnson

4686 Rt. 60 Gerry NY 14740 Town - City - Village Information for Inspection:

TCV CODE	TCV NAME	
0613	Town of Gerry	

Town of Gerry

**Jeffrey Johnson** 

## **REMARKS:**

All enclosures housing seized dogs must be structurally sound and kept in good repair to keep the dog contained and to protect it from injury. There must be no rust, jagged edges or sharp points. Damaged areas of kennels must be repaired or replaced to prevent dogs from ingesting any materials that may come loose from chewing and clawing the enclosure. Wood must be sealed if it is used for walls. Due to its porosity, concrete must be treated with a liquid sealer or hardener to make it waterproof. Waterproofing prevents water damage to concrete and allows thorough sanitation.

REPRESENTATIVE PRESENT FOR INSPECTION: TITLE: DCO

<b>REVIEWED BY:</b>	Inspector #: 64
REVIEWED DATE:	12/14/2022