NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 7/1/24 2:12 pm

JASON LEONARD 642 WOOD RD FREEVILLE NY 13068 Inspector #: 070

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound

No

At least 2 chain link runs have severely rusted or broken support pipe beams, at least 4 runs have very large holes in chain link with some rods bent inward posing a safety risk with 1 run having 3 holes large enough to pose an escape risk.

2. Housing area and equipment is sanitized regularly

Yes

3. Repairs are done when necessary

No

At least 2 chain link runs have severely rusted or broken support pipe beams, at least 4 runs have very large holes in chain link with some rods bent inward posing a safety risk with 1 run having 3 holes large enough to pose an escape risk. All runs have exposed/unsealed concrete on inside portion of runs, which prevent proper disinfection.

occupe home have expected ancealed controlled on molde person of rune, miner	p. 0 . 0 p
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE TCV NAME 5003 Town of Dryden

REMARKS:

TITLE: DCO

REPRESENTATIVE PRESENT FOR INSPECTION: **Jason Leonard**

Inspector #: 833 REVIEWED BY: 07/05/2024 REVIEWED DATE: