## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 10/31/24 12:45 pm

THE SPCA IN CATTARAUGUS COUNTY 2944 ROUTE 16 OLEAN NY 14760 Inspector #: 074

These are the findings of an inspection of your facility on the date(s) indicated above:

## 1. Shelter is structurally sound

No

In outdoor kennels, repairs needed on crumbling/missing concrete blocks. kennels not structurally sound and move when pushed on by dogs.

Dividing walls of several interior

2. Housing area and equipment is sanitized regularly

No

Rusted/corroded pipes/chain link and exposed wood in room being used as a kennel are unable to be cleaned/sanitized properly.

3. Repairs are done when necessary

No

In both interior and outdoor kennels, dividing walls and doors have rusted/corroded pipes with sharp edges exposed to the dogs. Chain link walls/doors of several kennels are excessively rusted/corroded. In room being used as a kennel, wood door framing has been chewed and is splintered.

4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
0403	Town of Carrollton
0421	Town of Napoli
0430	Town of Salamanca
0432	Town of Yorkshire
0427	Town of Portville
0431	Town of South Valley

## **REMARKS:**

All enclosures housing seized dogs must be structurally sound and kept in good repair to keep the dog contained and to protect it from injury. There must be no rust, jagged edges or sharp points. All surfaces within the primary enclosure must be replaced or repaired when worn or damaged. Dirty, rough and absorbent materials protect microorganisms and are difficult to clean, disinfect and deodorize. There must be no openings where an animal can become entrapped. Housing must be constructed and arranged to allow easy removal of the dog without injury. Repair or replace damaged sections to prevent dogs from ingesting any materials that may come loose from chewing and clawing the enclosure. Any openings where dogs can escape must be closed. Rust needs to be removed and surfaces repaired to allow proper sanitation.

REPRESENTATIVE PRESENT FOR INSPECTION:

**Arianna North** 

REVIEWED BY: Inspector #: 64
REVIEWED DATE: 11/08/2024

TITLE: Cat Cleaner REVIEWED DATE: