

MUNICIPAL SHELTER INSPECTION REPORT - DL-90Rating: **Satisfactory365**Purpose: **Inspection**DATE/TOA: **12/20/24 2:15 pm****CANEADEA MUNICIPAL SHELTER
9892 STATE RTE 19
HOUGHTON NY 14744**Inspector #: **074**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---|-----|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | Yes |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Yes |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Yes |

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
0212	Town of Caneadea
0213	Town of Centerville
0220	Town of Hume
0223	Town of Rushford
0208	Town of Belfast

REMARKS:

REPRESENTATIVE PRESENT FOR INSPECTION:
TITLE: **Operator (Public Works)**

Garret Peet

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **12/24/2024**