NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 2/18/25 1:21 pm

ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER 2976 COUNTY RD 48 CANANDAIGUA NY 14424 Inspector #: 80 Inspector #: 64

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	No
Housing area can not be santized properly, see remarks	
3. Repairs are done when necessary	No
Cracks, crevices, and missing mortar in cinder blocks are not repaired as necassary	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
3. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV NAME
Town of East Bloomfield
Town of Farmington
Town of Bristol
Town of Canadice
Town of Canandaigua
Town of Gorham
Town of Hopewell
Town of Manchester
Town of Naples
Town of Phelps
Town of Richmond
Town of Seneca
Town of South Bristol
Town of Victor
Town of West Bloomfield
City of Canandaigua
City of Geneva
Town of Geneva

REMARKS:

The mason blocks which make up the walls of the kennels in the housing area are porous and not sealed. There are large chunks of mortar missing between cinder blocks, which leaves large gaps, cracks and crevices. Due to this condition the kennel walls where dogs are housed are not able to be sanitized properly. Bare concrete and mason blocks require routine maintenance and repairs to allow proper cleaning and disinfection, and to maintain the structure of the kennels. It is recommended that some sort of permanent sealant is applied to prevent further water and structural damage and allow for thorough sanitation.

REPRESENTATIVE PRESENT FOR INSPECTION: William Martin REVIEWED BY: Inspector #: 64
TITLE: Shelter Director REVIEWED DATE: 02/21/2025