## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 5/1/25 12:30 pm

ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER 2976 COUNTY RD 48 CANANDAIGUA NY 14424 Inspector #: 80
Inspector #: 64

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound No			
Several enclosures have holes, loose bars, damaged or bent wire causing	points/edges, and large gaps which		
could allow a dog to escape or cause injury.  2. Housing area and equipment is sanitized regularly	No		
Housing area can not be sanitized properly, see remarks.			
3. Repairs are done when necessary	No		
Cracks, crevices, and missing mortar in cinder blocks are not repaired as necassary.			
4. Dogs are handled safely	Yes		
5. Adequate space is available for all dogs	Yes		
6. Light is sufficient for observation Yes			
7. Ventilation is adequate	Yes		
8. Drainage is adequate	Yes		
9. Temperature extremes are avoided	Yes		
10. Clean food and water is available and in ample amount  Yes			
11. Veterinary care is provided when necessary	Yes		
12. Dogs are euthanized humanely, by authorized personnel	Yes		
13. Complete intake and disposition records are maintained for all seized dogs	Yes		
14. Dogs transferred for purposes of adoption in compliance with Article 7  Yes			
15. Redemption period is observed before adoption, euthanasia or transfer Yes			
16. Owners of identified dogs are properly notified Yes			
7. Redeemed dogs are licensed before release Yes			
18. Proper impoundment fees paid before dogs are released	Yes		
19. Written contract or lease with municipality	Yes		

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

## REMARKS:

The mason blocks which make up the walls of the kennels in the housing area are porous and not sealed. There are large chunks of mortar missing between cinder blocks, which leaves large gaps, cracks and crevices. Due to this condition the kennel walls where dogs are housed are not be able to be sanitized properly. Bare concrete and mason blocks require routine maintenance and repairs to allow proper cleaning and disinfection and maintain the structure of the kennels. It is recommended that some sort of permanent sealant is applied to prevent further water and structural damage and allow for thorough sanitation.

All enclosures housing seized dogs must be structurally sound and kept in good repair to keep the dog contained and to protect it from injury. There must be no rust, jagged edges or sharp points. Damaged areas of kennels must be repaired or replaced to prevent dogs from ingesting any materials that may come loose from chewing and clawing the enclosure. Wood must be sealed if it is used for walls. Due to its porosity, concrete must be treated with a liquid sealer or hardener to make it waterproof. Waterproofing prevents water damage to concrete and allows thorough sanitation.

REPRESENTATIVE PRESENT FOR INSPECTION: TITLE: ACO

Timothy Kesel

REVIEWED BY: Inspector #: 64
REVIEWED DATE: 05/07/2025