NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235



# MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30** Purpose: **Inspection**

DATE/TOA: **6/12/25 1:30 pm**

**ONTARIO COUNTY HUMANE SOCIETY INC**
**HAPPY TAILS ANIMAL SHELTER**
**2976 COUNTY RD 48**
**CANANDAIGUA NY 14424**

Inspector #: **80**
Inspector #: **64**

These are the findings of an inspection of your facility on the date(s) indicated above:

| | |
|---|---|
| **1. Shelter is structurally sound** | No |
| *Several enclosures have holes, loose bars, damaged or bent wire causing points/edges, and large gaps which could allow a dog to escape or cause injury.* | |
| **2. Housing area and equipment is sanitized regularly** | No |
| *Housing area can not be sanitized properly, see remarks.* | |
| **3. Repairs are done when necessary** | No |
| *Cracks, crevices, and missing mortar in cinder blocks are not repaired as necassary.* | |
| **4. Dogs are handled safely** | Yes |
| **5. Adequate space is available for all dogs** | Yes |
| **6. Light is sufficient for observation** | Yes |
| **7. Ventilation is adequate** | Yes |
| **8. Drainage is adequate** | Yes |
| **9. Temperature extremes are avoided** | Yes |
| **10. Clean food and water is available and in ample amount** | Yes |
| **11. Veterinary care is provided when necessary** | Yes |
| **12. Dogs are euthanized humanely, by authorized personnel** | Yes |
| **13. Complete intake and disposition records are maintained for all seized dogs** | Yes |
| **14. Dogs transferred for purposes of adoption in compliance with Article 7** | Yes |
| **15. Redemption period is observed before adoption, euthanasia or transfer** | Yes |
| **16. Owners of identified dogs are properly notified** | Yes |
| **17. Redeemed dogs are licensed before release** | Yes |
| **18. Proper impoundment fees paid before dogs are released** | Yes |
| **19. Written contract or lease with municipality** | Yes |

Town - City - Village Information for Inspection:

| TCV CODE | TCV NAME |
|---|---|
| 3204 | Town of East Bloomfield |
| 3205 | Town of Farmington |
| 3201 | Town of Bristol |
| 3202 | Town of Canadice |
| 3203 | Town of Canandaigua |
| 3207 | Town of Gorham |
| 3208 | Town of Hopewell |
| 3209 | Town of Manchester |
| 3210 | Town of Naples |
| 3211 | Town of Phelps |
| 3212 | Town of Richmond |
| 3213 | Town of Seneca |
| 3214 | Town of South Bristol |
| 3215 | Town of Victor |
| 3216 | Town of West Bloomfield |
| 3217 | City of Canandaigua |
| 3218 | City of Geneva |
| 3206 | Town of Geneva |

REMARKS:

**The mason blocks which make up the walls of the kennels in the housing area are porous and not sealed. There are large chunks of mortar missing between cinder blocks, which leaves large gaps, cracks and crevices. Due to this condition the kennel walls where dogs are housed are not be able to be sanitized properly. Bare concrete and mason blocks require routine maintenance and repairs to allow proper cleaning and disinfection and maintain the structure of the kennels. It is recommended that some sort of permanent sealant is applied to prevent further water and structural damage and allow for thorough sanitation.**

**All enclosures housing seized dogs must be structurally sound and kept in good repair to keep the dog contained and to protect it from injury.There must be no rust, jagged edges or sharp points. Damaged areas of kennels must be repaired or replaced to prevent dogs from ingesting any materials that may come loose from chewing and clawing the enclosure. Wood must be sealed if it is used for walls. Due to its porosity, concrete must be treated with a liquid sealer or hardener to make it waterproof. Waterproofing prevents water damage to concrete and allows thorough sanitation.**

REPRESENTATIVE PRESENT FOR INSPECTION: **Timothy Kesel**
TITLE: **ACO**

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **06/20/2025**