

## MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**Purpose: **Inspection**DATE/TOA: **9/5/25 1:00 pm**

**THE SPCA IN CATTARAUGUS COUNTY**  
**2944 ROUTE 16**  
**OLEAN NY 14760**

Inspector #: **85**Inspector #: **79**


---

These are the findings of an inspection of your facility on the date(s) indicated above:

---

**1. Shelter is structurally sound**

No

*In outdoor kennels, repairs needed on crumbling/missing concrete blocks. Dividing walls of several interior kennels not structurally sound. A few areas of wall have large enough holes for dogs to crawl through between kennels.*

**2. Housing area and equipment is sanitized regularly**

No

*Rusted/corroded pipes/chain link and unsealed concrete block walls are unable to be cleaned/sanitized properly. Buildup of feces & debris in troughs and covering/blocking openings of outdoor drains.*

**3. Repairs are done when necessary**

No

*In both interior and outdoor kennels, dividing walls and doors have rusted/corroded pipes with sharp edges exposed to the dogs. Chain link walls/doors of several kennels are excessively rusted/corroded. Crumbling/cracked/missing concrete block in exterior runs. Missing/damaged tiles on walls of interior runs. One guillotine door is not properly seated in track, and the safety chain is not connected to the wall- the door is at risk of falling and causing injury. Several chain link panels on dividing walls and doors in need of repair. Gaps in chainlink doors could allow for potential escape and/or injury. 2nd play yard on the pond side of the building has multiple areas where dogs have previously dug under the chainlink fence that are now being barricaded by concrete blocks held with exposed rebar in the enclosure.*

**4. Dogs are handled safely**

Yes

**5. Adequate space is available for all dogs**

Yes

**6. Light is sufficient for observation**

Yes

**7. Ventilation is adequate**

Yes

**8. Drainage is adequate**

Yes

**9. Temperature extremes are avoided**

Yes

**10. Clean food and water is available and in ample amount**

Yes

**11. Veterinary care is provided when necessary**

Yes

**12. Dogs are euthanized humanely, by authorized personnel**

Yes

**13. Complete intake and disposition records are maintained for all seized dogs**

Yes

**14. Dogs transferred for purposes of adoption in compliance with Article 7**

Yes

**15. Redemption period is observed before adoption, euthanasia or transfer**

Yes

**16. Owners of identified dogs are properly notified**

Yes

**17. Redeemed dogs are licensed before release**

Yes

**18. Proper impoundment fees paid before dogs are released**

Yes

**19. Written contract or lease with municipality**

No

*Primary holding contracts with the City of Olean and the Towns of Conewango, Franklinville, Ischua, Little Valley, Napoli, South Valley, and Yorkshire have all expired.*

---

Town - City - Village Information for Inspection:

---

TCV CODE	TCV NAME
0410	Town of Franklinville
0403	Town of Carrollton
0405	Town of Conewango
0415	Town of Ischua
0417	Town of Little Valley
0421	Town of Napoli
0430	Town of Salamanca
0432	Town of Yorkshire
0433	City of Olean
0427	Town of Portville
0431	Town of South Valley

## REMARKS:

All enclosures housing seized dogs must be structurally sound and kept in good repair to keep the dog contained and to protect it from injury. There must be no rust, jagged edges or sharp points. All surfaces within the primary enclosure must be replaced or repaired when worn or damaged. Dirty, rough and absorbent materials (such as unsealed concrete) protect microorganisms and are difficult to clean, disinfect and deodorize. There must be no openings where an animal can become entrapped. Housing must be constructed and arranged to allow easy removal of the dog without injury. Any openings where dogs can escape must be closed.

REPRESENTATIVE PRESENT FOR INSPECTION: **Olivia Ingalls**  
TITLE: **Team Lead**

REVIEWED BY: **Inspector #: 833**  
REVIEWED DATE: **09/05/2025**