NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory182** Purpose: **Inspection**

DATE/TOA: **5/10/12 10:15 am**

WAYLAND MUNICIPAL SHELTER
1118 STATE RTE. 21
WAYLAND NY 14572

Inspector #: **809**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Not Applicable
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
4609	Town of Cohocton
4628	Town of Wayland

REMARKS:

All of the deficiencies noted during the last inspection have been addressed. The outside kennels have been adjusted to allow water to drain out and into the culvert which leads to the septic tank. The indoor kennels have been repaired such that the upper wooden supports have been replaced with galvanized stainless steel bars which are sturdy and easily cleaned/disinfected. A fan has been installed to provide adequate ventilation. The hole in the fiberglass wall on the west side of the structure has been repaired also.

The towns (Wayland and Cohocton) should be commended for taking the steps to bring the shelter into compliance by working as a team. This cooperative effort has resulted in a positive outcome of this inspection. A sign has been placed to identify the location of the shelter from the road. It is anticipated that an outdoor exercise area will be constructed to provide more room for the dogs to walk around while their kennels are cleaned.

The entrance into the shelter is still obstructed by the large mounds of dirt/salt that is stored at the highway department. The area in front of the doorway to the shelter is littered with broken pieces of blacktop and stone. This could prove hazardous to anyone entering the shelter. The indoor kennel doors have rusted hinges with wood dividers. These will need to be replaced at some time in the future before they become unsafe or structurally unsound.

REPRESENTATIVE PRESENT FOR INSPECTION: **Mike Matthews**
TITLE: **assisant shelter manager**

REVIEWED BY:
REVIEWED DATE: **05/15/2012**