

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory365**

Purpose: **Inspection**

DATE/TOA: **12/15/12 2:00 pm**

**GREENWOOD TOWN SHELTER
 2738 STATE RTE 248
 GREENWOOD NY 14839**

Inspector #: **809**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Not Applicable |
| 3. Repairs are done when necessary | Yes |
| 4. Dogs are handled safely | Not Applicable |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| <i>There are no inside drains, but water can be flushed through the kennels to the outside drainage area.</i> | |
| 9. Temperature extremes are avoided | Yes |
| <i>Heat lamps are available.</i> | |
| 10. Clean food and water is available and in ample amount | Not Applicable |
| 11. Veterinary care is provided when necessary | Not Applicable |
| 12. Dogs are euthanized humanely, by authorized personnel | Not Applicable |
| 13. Complete intake and disposition records are maintained for all seized dogs | Not Applicable |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Not Applicable |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Not Applicable |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Not Applicable |
| 18. Proper impoundment fees paid before dogs are released | Not Applicable |
| 19. Written contract or lease with municipality | Not Applicable |

Town - City - Village Information for Inspection:

<u>TCV CODE</u>	<u>TCV NAME</u>
4614	Town of Greenwood

REMARKS:

The shelter has not been used since Rick Harrison resigned as DCO for the town of Greenwood. Gary Hadsell is the DCO/shelter manager for the town of Greenwood. It is anticipated that the town of Greenwood will contract with the town of Canisteo for shelter services and use the Greenwood shelter as an overflow/back-up facility. The interior of the shelter is in excellent shape. New aluminum sheeting has been placed on all the walls to facilitate cleaning and disinfection as well as to prevent dogs from chewing the walls.

REPRESENTATIVE PRESENT FOR INSPECTION: **Gary Hadsell**
TITLE: **shelter manager**

REVIEWED BY:
REVIEWED DATE: **12/17/2012**