NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory365** Purpose: **Inspection**

DATE/TOA: **11/13/13 11:00 am**

ONTARIO COUNTY HS
2976 COUNTY RD 48
CANANDAIGUA NY 14424

Inspector #: **56**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes

A work order was immediately submitted for repairs needed on approximately 6 kennel doors in Ward 1. The chain links at the bottom of the doors have been pulled apart by dogs creating openings and causing damage to the links. Two of the kennels had links with sharp edges which could injure a dog. It was recommended that those two kennels not house dogs until repairs were made.

4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes

Dr. Peter Brown, Macedon Veterinary Care or Monroe Veterinary Associates provide care.

It was discussed that seized dogs suffering from illness or injury must receive prompt treatment by a licensed veterinarian.

12. Dogs are euthanized humanely, by authorized personnel	Yes

Certified Euthanasia Technician Linda Albanese is on staff. Renewal of her certification has been applied for as the current certificate expires 11/23/13.

13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

REMARKS:

It is recommended that the cinder block walls in the kennel rooms be covered with a waterproofing sealant. Some kennels had dark spots on the walls where water had been absorbed and not yet dried. Two kennels had cinder block where some of the mortar between them was missing. Sealing will prevent water damage and allow for thorough sanitation.

REPRESENTATIVE PRESENT FOR INSPECTION: **Linda Albanese**
TITLE: **Shelter Manager**

REVIEWED BY: **Inspector #: 14**
REVIEWED DATE: **11/18/2013**