NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Satisfactory182 Purpose: Inspection

DATE/TOA: 1/9/15 1:45 pm

CANISTEO MUNICIPAL SHELTER 67 DEPOT ST. CANISTEO NY 14823 Inspector #: 809

hese are the findings of an insp	ection of your facility	on the date(s) inc	licated above
----------------------------------	-------------------------	--------------------	---------------

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	No

The air is stale in the kennel. More air movement would provide a more desirable environment. It is anticipated that an exhaust fan will be installed within the next six months.

8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes

12. Dogs are euthanized humanely, by authorized personnel Not Applicable

13. Complete intake and disposition records are maintained for all seized dogs
 Yes

 14. Dogs transferred for purposes of adoption in compliance with Article 7
 Many dogs are transferred to another municipal shelter or an incorporated dog rescue group.

 15. Redemption period is observed before adoption, euthanasia or transfer
 Yes

16. Owners of identified dogs are properly notifiedNot Applicable17. Redeemed dogs are licensed before releaseNot Applicable18. Proper impoundment fees paid before dogs are releasedNot Applicable

19. Written contract or lease with municipality

Yes

There is a contract with the towns of Hartsville and Jasper.

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
4607	Town of Canisteo
4615	Town of Hartsville
4619	Town of Jasper

REMARKS:

TITLE: shelter manager

The shelter is clean and the installation of the upper wall covering has almost been completed. The sink drains directly into the main drainage sluice now. Although the air is still "stale", it is anticipated that a large exhaust fan will be installed in the near future.

No dogs were euthanized or redeemed in the past 6 months. All dogs were transferred for adoption as per Article 7.

REPRESENTATIVE PRESENT FOR INSPECTION:

Gary Hadsell

REVIEWED BY:

REVIEWED DATE: 01/15/2015