

## MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**Purpose: **Inspection**DATE/TOA: **7/29/15 1:15 pm**

**MONTGOMERY COUNTY SPCA**  
**1007 RT 5S**  
**AMSTERDAM NY 12010**

Inspector #: **54**


---

These are the findings of an inspection of your facility on the date(s) indicated above:

---

- |   |                |
|---|----------------|
| <b>1. Shelter is structurally sound</b>   | No             |
| <i>Eight outdoor runs at the rear of the kennel and eight outdoor runs at the front of the kennel building; the pipes that compromise the door frames that the chain link is attached to, are rusty, broken and have jagged edges at both corners at the bottom of the door, and the pipe that connects the corners at the bottom of the door are severely rusted. Additionally on the inside of the kennel at the front of the building, the fifth run in from the entrance door has a rusted pipe that is not secured at the bottom of the door frame. The inside quarantine area, the second run from the right, the lower right corner, the end of the pipe is rusted and has sharp edges. These areas pose a risk of injury to the dogs contained therein and cannot be effectively cleaned and disinfected to prevent the spread of diseases.</i> |                |
| <b>2. Housing area and equipment is sanitized regularly</b>   | Yes            |
| <b>3. Repairs are done when necessary</b>   | No             |
| <i>Bolts sticking out from the concrete around the door openings in the outdoor runs need to be removed. Several areas in the concrete of the outdoor runs, where there are large cracks, chips and holes need to be filled in. Seven outdoor enclosures plus one attached to the quarantine area are freestanding kennels and have several areas where patches have been attempted that still need repair to remove the loose or sharp wire or pipes. Several of these enclosures have wire that is unsecured at the bottom. Holes that the dogs have dug in the dirt at the back corners of a couple of these enclosures need to be filled in.</i>  |                |
| <b>4. Dogs are handled safely</b>   | Yes            |
| <b>5. Adequate space is available for all dogs</b>  | Yes            |
| <b>6. Light is sufficient for observation</b>   | Yes            |
| <b>7. Ventilation is adequate</b>   | Yes            |
| <b>8. Drainage is adequate</b>  | Yes            |
| <b>9. Temperature extremes are avoided</b>  | Yes            |
| <b>10. Clean food and water is available and in ample amount</b>  | Yes            |
| <b>11. Veterinary care is provided when necessary</b>   | Yes            |
| <b>12. Dogs are euthanized humanely, by authorized personnel</b>  | Yes            |
| <b>13. Complete intake and disposition records are maintained for all seized dogs</b>   | Yes            |
| <b>14. Dogs transferred for purposes of adoption in compliance with Article 7</b>   | Yes            |
| <b>15. Redemption period is observed before adoption, euthanasia or transfer</b>  | Yes            |
| <b>16. Owners of identified dogs are properly notified</b>  | Not Applicable |
| <b>17. Redeemed dogs are licensed before release</b>  | Yes            |
| <b>18. Proper impoundment fees paid before dogs are released</b>  | Yes            |

**19. Written contract or lease with municipality**

No

*No current signed contract for the Town of Rotterdam only.*

*All other contracted municipalities are current with expiration dates as follows; Town of Amsterdam & Florida 12/31/16, City of Amsterdam 6/30/17.*

---

Town - City - Village Information for Inspection:

---

<b>TCV CODE</b>	<b>TCV NAME</b>
2704	Town of Florida
2701	Town of Amsterdam
4205	Town of Rotterdam
2711	City of Amsterdam
4204	Town of Princetown

REMARKS:

**N/A=DCO handles.**

**Several areas of chain link wire that are rusty and pitted need resurfacing as they cannot be effectively cleaned and disinfected to prevent the spread of disease.**

**No improvements or repairs have been made since the previous inspection.**

REPRESENTATIVE PRESENT FOR INSPECTION: **Antonio Baker**  
TITLE: **Manager**

REVIEWED BY: **Inspector #: 50**  
REVIEWED DATE: **08/11/2015**