NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30** Purpose: **Inspection**

DATE/TOA: **7/29/15 1:15 pm**

MONTGOMERY COUNTY SPCA
1007 RT 5S
AMSTERDAM NY 12010

Inspector #: **54**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	No

Eight outdoor runs at the rear of the kennel and eight outdoor runs at the front of the kennel building; the pipes that compromise the door frames that the chain link is attached to, are rusty, broken and have jagged edges at both corners at the bottom of the door, and the pipe that connects the corners at the bottom of the door are severely rusted. Additionally on the inside of the kennel at the front of the building, the fifth run in from the entrance door has a rusted pipe that is not secured at the bottom of the door frame. The inside quarantine area , the second run from the right, the lower right corner, the end of the pipe is rusted and has sharp edges. These areas pose a risk of injury to the dogs contained therein and cannot be effectively cleaned and disinfected to prevent the spread of diseases.

2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	No

Bolts sticking out from the concrete around the door openings in the outdoor runs need to be removed. Several areas in the concrete of the outdoor runs, where there are large cracks, chips and holes need to be filled in . Seven outdoor enclosures plus one attached to the quarantine area are freestanding kennels and have several areas where patches have been attempted that still need repair to remove the loose or sharp wire or pipes . Several of these enclosures have wire that is unsecured at the bottom. Holes that the dogs have dug in the dirt at the back corners of a couple of these enclosures need to be filled in.

4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Not Applicable
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes

19. Written contract or lease with municipality No

No current signed contract for the Town of Rotterdam only.
All other contracted municipalities are current with expiration dates as follows; Town of Amsterdam & Florida 12/31/16, City of Amsterdam 6/30/17.

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
2704	Town of Florida
2701	Town of Amsterdam
4205	Town of Rotterdam
2711	City of Amsterdam
4204	Town of Princetown

REMARKS:

N/A=DCO handles.
Several areas of chain link wire that are rusty and pitted need resurfacing as they cannot be effectively cleaned and disinfectant to prevent the spread of disease.

No improvements or repairs have been made since the previous inspection.

REPRESENTATIVE PRESENT FOR INSPECTION: **Antonio Baker**
TITLE: **Manager**

REVIEWED BY: **Inspector #: 50**
REVIEWED DATE: **08/11/2015**