

**MUNICIPAL SHELTER INSPECTION REPORT - DL-90**Rating: **Satisfactory182**Purpose: **Inspection**DATE/TOA: **10/6/15 2:00 pm****GREENWOOD TOWN SHELTER  
2738 STATE RTE 248  
GREENWOOD NY 14839**Inspector #: **809**

---

These are the findings of an inspection of your facility on the date(s) indicated above:

---

- |  |                |
|--|----------------|
| 1. Shelter is structurally sound   | Yes            |
| 2. Housing area and equipment is sanitized regularly                           | Yes            |
| 3. Repairs are done when necessary   | Yes            |
| 4. Dogs are handled safely   | Yes            |
| 5. Adequate space is available for all dogs                                    | Yes            |
| 6. Light is sufficient for observation   | Yes            |
| 7. Ventilation is adequate   | Yes            |
| 8. Drainage is adequate  | Yes            |
| 9. Temperature extremes are avoided  | Yes            |
| 10. Clean food and water is available and in ample amount                      | Yes            |
| 11. Veterinary care is provided when necessary                                 | Not Applicable |
| 12. Dogs are euthanized humanely, by authorized personnel                      | Not Applicable |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes            |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7     | Yes            |
| 15. Redemption period is observed before adoption, euthanasia or transfer      | Yes            |
| 16. Owners of identified dogs are properly notified                            | Not Applicable |
| 17. Redeemed dogs are licensed before release                                  | Not Applicable |
| 18. Proper impoundment fees paid before dogs are released                      | Yes            |
| 19. Written contract or lease with municipality                                | Yes            |

---

**Town - City - Village Information for Inspection:**

---

<b>TCV CODE</b>	<b>TCV NAME</b>
4614	Town of Greenwood
4630	Town of West Union

**REMARKS:**

**This shelter is shared by the towns of Greenwood and West Union. The DCO for each town is responsible for the disposition of their own dogs. It is recommended that some painting be done to improve the appearance of the shelter. The wooden parts of the dog doors should be replaced with metal or other impervious material since the dogs chew on the wooden frame (bottom of dog door opening only).**

**The shelter is clean and neat.**

**REPRESENTATIVE PRESENT FOR INSPECTION:**  
**TITLE: shelter manager**

**Gary Hadsell**

**REVIEWED BY:**  
**REVIEWED DATE: 10/16/2015**