

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**

Purpose: **Inspection**

DATE/TOA: **2/19/16 12:15 pm**

**MONTGOMERY COUNTY SPCA
 1007 RT 5S
 AMSTERDAM NY 12010**

Inspector #: **54**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---|----------------|
| 1. Shelter is structurally sound | No |
| <i>Six outdoor runs at the front of the kennel building have rusty sharp edges at the bottom of the pipes of the door frame. Four indoor runs at the front of the kennel building have rusty sharp edges at the bottom of the pipes of the door frame including one unattached broken pipe. One or two indoor runs at the back of the kennel building have rusty sharp edges at the bottom of the pipes of the door frame. One freestanding kennel outside to the left of the parking lot has sharp pipes protruding into the kennel. These areas pose a risk of injury to the dogs contained therein and cannot be effectively cleaned and disinfected to prevent the spread of disease.</i> | |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | No |
| <i>One outdoor run in the isolation area has a four to five inch opening in the chain link fence at the lower corner.</i> | |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Yes |

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
2704	Town of Florida
2701	Town of Amsterdam
4205	Town of Rotterdam
2711	City of Amsterdam

REMARKS:

N/A=handled by DCO.

The chain link wire that was rusty and pitted has been resurfaced. There are currently five freestanding outdoor kennels, one in the isolation area and four to the left of the parking lot. All but one have been rendered unusable by removal of the doors. The one kennel that is still in use is the one with the sharp pipes protruding inward as indicated in section one of this report. All sharp and broken wire or pipes and previous unsafe patches to the chain link will need to be replaced or repaired before dogs can be placed in these outdoor kennels.

REPRESENTATIVE PRESENT FOR INSPECTION: Antonio Baker
TITLE: Manager

REVIEWED BY: Inspector #: 50
REVIEWED DATE: 02/29/2016