

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory⁹¹**

Purpose: **Inspection**

DATE/TOA: **3/30/16 1:30 pm**

**MONTGOMERY COUNTY SPCA
 1007 RT 5S
 AMSTERDAM NY 12010**

Inspector #: **54**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---------------------------------------------------------------------------------------|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | Yes |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Yes |

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
2704	Town of Florida
2701	Town of Amsterdam
4205	Town of Rotterdam
2711	City of Amsterdam

REMARKS:**N/A=handled by DCO**

Sharp and rusty or broken pipes that comprise the kennel doors in the outdoor and indoor kennels have been repaired. The freestanding kennel to the left of the parking lot has had the sharp pipe removed and can be used. One other freestanding kennel to the left of the parking lot has had the damaged chain link switched to be at the top of the kennel out of the dogs reach, this kennel may now be used. One outdoor kennel door frame at the front of the building, has a slight sharpness to the bottom corner that needs to be filed smooth. This run has a 'do not use' sign on the door until this is done. The other two freestanding kennels at the left of the parking lot and the one free standing kennel next to isolation housing have the doors off and are not in use. These will need all sharp protruding wire repaired and any holes in the wire fixed before they are put into use in the warmer weather.

REPRESENTATIVE PRESENT FOR INSPECTION: **Anthonio Baker**
TITLE: **Manager**

REVIEWED BY: **Inspector #: 50**
REVIEWED DATE: **03/31/2016**