

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory60**

Purpose: **Inspection**

DATE/TOA: **4/8/16 10:15 am**

**TOWN OF JOHNSTOWN ANIMAL SHELTER
 352 COUNTY HWY 122
 MAPLE AVE
 GLOVERSVILLE NY 12078**

Inspector #: **54**

Inspector #: **50**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---------------------------------------------------------------------------------------|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | Yes |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Not Applicable |

Municipal shelter

 Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
1705	Town of Johnstown

REMARKS:

N/A=DCO handles notifying owner of identified dogs seized.

Latches have been installed on all but two runs. Two of the runs need the latches moved in so more of the door frame connects into the latch. Hooks should be used to secure the latches so dogs cannot flip them up. One run has had plexi glass installed to alleviate the spaces a small dog could escape or become lodged in. The two largest runs still under construction, will need plexi glass installed where the vertical steel bars connect to the support pipes at the lower edge and half way up to prevent a limb or dog's head from becoming lodged. Lighting has been improved. Food storage, food & water receptacles, cots, cleaning supplies and equipment have been provided. The hot water and the utility sink are still not operational to effectively clean food & water receptacles. The disinfectant provided should be checked to see if it is effective used with cold water.

Currently the shelter can safely accommodate a few seized dogs, with four of the runs as mentioned above not usable. A re inspection of this new shelter will occur in 60 days.

REPRESENTATIVE PRESENT FOR INSPECTION:

Nancy Hart/Richard

REVIEWED BY:

Inspector #: 50

TITLE: Johnstown DCO/City of Glove

Schuyler

REVIEWED DATE:

04/11/2016