NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 8/31/17 1:15 pm

THE SPCA IN CATTARAUGUS COUNTY 2944 ROUTE 16 OLEAN NY 14760 Inspector #: 68

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound

Yes

2. Housing area and equipment is sanitized regularly

Yes

3. Repairs are done when necessary

No

The chain link above both kennel partitions containing "Bang" and "Gert" need to be covered to protect the dogs from injury.

"Gert's" guillotine door cable needs to be repaired and out of reach to be chewed on.

The kennels inside should be cleaned from cobwebs and rusted areas spray painted.

Outside kennels have rusty chains, pipes and crate dividers that serve no structural purpose to the kennels or safety of the dogs located in and near the kennels that should be cleaned up

Yes
Yes

[&]quot;Cooper's" Door needs to have the door latch adjusted to prevent escape.

[&]quot;Gee's" outside kennel door needs the L-bracket reattached to the door.

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
0411	Town of Freedom
0215	Town of Cuba
0423	Town of Olean
0429	Town of Red House
0433	City of Olean
	0411 0215 0423 0429

REMARKS:

REPRESENTATIVE PRESENT FOR INSPECTION: TITLE: Receptionist

Marrissa Thurst

REVIEWED BY: Inspector #: 14
REVIEWED DATE: 09/05/2017