

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**Purpose: **Inspection**DATE/TOA: **11/20/17 1:00 pm**

TOWN OF OWEGO DOG SHELTER
398 TAYLOR RD
OWEGO NY 13827

Inspector #: **14**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|--|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | No |
| <i>There are a few areas of rust on the framework of the two kennels that are useable. They need to be painted to allow for effective cleaning and disinfection. This was noted on the inspection report of 6/20/17 and given another extension to get taken care of on the 9/28/17 inspection report.</i> | |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | No |
| <i>Furnace was malfunctioning, only running for a short time then shutting off.</i> | |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Yes |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Not Applicable |

Town - City - Village Information for Inspection:

| TCV CODE | TCV NAME |
|-----------------|-----------------|
| 4906 | Town of Owego |

REMARKS:

One dog was present at the time of the inspection. Due to the malfunctioning furnace, the dog was moved to a different kennel that had a heat lamp installed in it.

On previous inspections, three kennels had been approved for use as the others need significant repair. The inspector noticed on this inspection that the outside kennel door on one of the approved kennels had been damaged and a grate installed over the area. This kennel should not be used until the chain link has either been repaired or replaced. Therefore, the shelter now has two kennels that are approved for housing.

Seizure record for dog being housed was on file at the shelter. Records for any other dog that has been sheltered at the facility between inspections should also be on file at the shelter.

REPRESENTATIVE PRESENT FOR INSPECTION: Jeff Ford
TITLE: Deputy DCO

REVIEWED BY: Inspector #: 833
REVIEWED DATE: 11/24/2017