NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30** Purpose: **Inspection**

DATE/TOA: **3/28/18 12:00 pm**

DELAWARE VALLEY HS
101 E MAIN STREET
SIDNEY NY 13838

Inspector #: **54**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	No
Old side kennel in rear, one run has rusty pipes at the bottom of the chain link run that have jagged edges. One run on the front has a broken pipe with jagged edges below the chain link run door.	
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	No
Old side rear kennel has two runs that have scratched and chewed wood that cannot effectively be cleaned and disinfected to prevent the spread of disease. This wood has been used to patch holes in the wall on the side of the door opening to the inside portion of the run.	
New side kennel has three runs where the frame around the dog door that separates the runs has areas that are chewed exposing bare wood and areas chewed through leaving an opening in the wall.	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Not Applicable
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3615	Town of Otego
1220	Village of Sidney
1216	Town of Sidney
3622	Town of Unadilla
1207	Town of Franklin

REMARKS:

N/A=handled by DCO

REPRESENTATIVE PRESENT FOR INSPECTION: **Erin Johnson**
TITLE: **Manager**

REVIEWED BY: **Inspector #: 50**
REVIEWED DATE: **03/29/2018**