

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**

Purpose: **Inspection**

DATE/TOA: **11/20/19 1:10 pm**

**ONTARIO COUNTY HUMANE SOCIETY INC
 HAPPY TAILS ANIMAL SHELTER
 2976 COUNTY RD 48
 CANANDAIGUA NY 14424**

Inspector #: **56**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|--|-----|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | No |
| <i>Chain link at the bottom of a gate on an occupied dog run was intertwined with a chain dog leash in order to secure damaged links to the base bar.
See "REMARKS".</i> | |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Yes |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | Yes |

 Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

REMARKS:

Regarding repairs: Broken wires pose a risk of injury and should be properly repaired in a timely fashion or the enclosure not used to house a dog.

Note: It was discussed that cinder blocks in the dog kennel area appear to be unsealed as they were wet from the morning cleaning. It is recommended that porous surfaces be sealed to prevent water damage and allow for thorough sanitation. It would also allow for a quicker drying time and alleviate extended damp conditions in the housing area.

REPRESENTATIVE PRESENT FOR INSPECTION:
TITLE: **Shelter Manager**

Diane Faas

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **12/20/2019**