NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

These are the findings of an inspection of your facility on the date(s) indicated above:

Rating: Satisfactory365 Purpose: Inspection

DATE/TOA: 12/4/19 12:45 pm

Yes

Yes

WAYNE COUNTY HUMANE SOCIETY 1475 COUNTY HOUSE ROAD LYONS NY 14485 Inspector #: 56

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes

3. Repairs are done when necessary See "REMARKS".

4. Dogs are handled safely Yes

5. Adequate space is available for all dogs

6. Light is sufficient for observation

Yes

7. Ventilation is adequate Yes

8. Drainage is adequate Yes

9. Temperature extremes are avoided Yes10. Clean food and water is available and in ample amount Yes

11. Veterinary care is provided when necessary

Yes

12. Dogs are euthanized humanely, by authorized personnel
Yes

13. Complete intake and disposition records are maintained for all seized dogs

Yes

14. Dogs transferred for purposes of adoption in compliance with Article 7 Yes

15. Redemption period is observed before adoption, euthanasia or transfer

Yes

To read in particular portion is a social and particular and an articular and articula

16. Owners of identified dogs are properly notifiedYes17. Redeemed dogs are licensed before releaseYes

18. Proper impoundment fees paid before dogs are released Yes

19. Written contract or lease with municipality

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
5403	Town of Galen
5401	Town of Arcadia
5402	Town of Butler
5404	Town of Huron
5405	Town of Lyons
5406	Town of Macedon
5407	Town of Marion
5408	Town of Ontario
5409	Town of Palmyra
5410	Town of Rose
5411	Town of Savannah
5412	Town of Sodus
5413	Town of Walworth
5414	Town of Williamson
5415	Town of Wolcott

REMARKS:

TITLE: Shelter Manager

The area used to hold dogs temporarily while the main facility is being cleaned is showing age and wear. Concrete floors have extensive cracks in some places. Kennel chain link is becoming rust covered. Sanitation is difficult to attain on rough and rusty surfaces.

REPRESENTATIVE PRESENT FOR INSPECTION:

Mark Plyter

REVIEWED BY: Inspector #: 64

REVIEWED DATE: 01/08/2020