NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory365** Purpose: **Inspection**

DATE/TOA: **12/2/20 12:15 pm**

TOWN OF ROCHESTER SHELTER
50 SCENIC ROAD
ACCORD NY 12404

Inspector #: **67**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
5102	Town of Esopus
5108	Town of Marbletown
5111	Town of Olive
5113	Town of Rochester
5119	Town of Wawarsing
5110	Town of New Paltz

REMARKS:

Please note future repairs needed. Exterior run 3 from entrance has broken chain link fence support that needs replacing/repair. Wood supporting fencing at in/out doors needs replacing/ re sealing for dogs to occupy in the future. Dog Control officer noted that rain water from previous storm flooded back into interior kennels via seepage through in/out entries and concrete walls; may want to consider sealing/correction to prevent future flooding.

REPRESENTATIVE PRESENT FOR INSPECTION: **Jill Shufeldt**
TITLE: **DCO**

REVIEWED BY: **Inspector #: 18**
REVIEWED DATE: **12/03/2020**