NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory182** Purpose: **Inspection**

DATE/TOA: **12/22/20 1:30 pm**

HUMANE SOCIETY OF WALDEN
2489 ALBANY POST ROAD
WALDEN NY 12586

Inspector #: **67**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes

Kennels 2 and 7 and "back side of building" previously needing repair are not housing dogs at the time of inspection. Big signs are posted on interior and exterior kennels in question stating, " DO NOT USE."
Entry side exterior kennels 1,2, and 4 have had cross bars sanded and resealed. Exterior run on "back side" of building labeled 11 has had concrete repair at guillotine door. Interior "front cage/pen" has had drain cover placed and holes in concrete from previous plumbing have been patched.

4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3304	Town of Crawford
4811	Town of Mamakating
3312	Town of Montgomery
3303	Town of Cornwall
5117	Town of Shawangunk
5119	Town of Wawarsing

REMARKS:

All exterior kennels connected to interior housing in need of repair were not in use at the time of inspection.

Please note the following repairs necessary before dogs are to utilize these runs.

Exterior runs on the entry side of the building, starting numerically from entry gate to runs - runs 1-5 require concrete cracks filled/ repaired and surface resealed. Runs 6-9 have "pitting" of concrete that needs repaired and resealed; runs 5 requires replacement of gate as cross bar support rusted through with sharp edges (safety concern); runs 9 &10 have chain link fencing supports rusted and broken in need of repair/replacing. (safety concern).Much of the chain link fencing is rusted and in need of attention.

Exterior kennel runs on the "back" side of the building, starting numerically from the entry gate to runs - kennel 1 has chain link support in need or repair/replacement; runs 2, 3, 4, & 7 have rusted (rusted through that concern for injury) cross bar supports in gate that require repair/replacement of gate. Kennel 9 needs crack in concrete floor repaired and resealed.

Interior "front cage/kennel" needs hole on wall repaired where lathe and insulation exposed.

Shelter staff member Rodriguez states that in speaking with a community member that helps with repairs; that concrete and resealing work cure/work best if done when weather warms.

REPRESENTATIVE PRESENT FOR INSPECTION: **Lisa Rodriguez / Marissa Ownes**

TITLE: **shelter staff / shelter manager**

REVIEWED BY: **Inspector #: 18**

REVIEWED DATE: **12/24/2020**