

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**

Purpose: **Inspection**

DATE/TOA: **7/6/21 1:45 pm**

**AYRES MEMORIAL ANIMAL SHELTER
 133 HILL TOP ROAD
 SPRAKERS NY 12166**

Inspector #: **54**

These are the findings of an inspection of your facility on the date(s) indicated above:

- | | |
|---|----------------|
| 1. Shelter is structurally sound | Yes |
| 2. Housing area and equipment is sanitized regularly | Yes |
| 3. Repairs are done when necessary | Yes |
| 4. Dogs are handled safely | Yes |
| 5. Adequate space is available for all dogs | Yes |
| 6. Light is sufficient for observation | Yes |
| 7. Ventilation is adequate | Yes |
| 8. Drainage is adequate | Yes |
| 9. Temperature extremes are avoided | Yes |
| 10. Clean food and water is available and in ample amount | Yes |
| 11. Veterinary care is provided when necessary | Yes |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes |
| 16. Owners of identified dogs are properly notified | Not Applicable |
| 17. Redeemed dogs are licensed before release | Yes |
| 18. Proper impoundment fees paid before dogs are released | Yes |
| 19. Written contract or lease with municipality | No |

No current signed contract for the following Towns & Villages; Town of Glen & Charleston, Village's of Ft. Plain, Fultonville & Canajoharie

 Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
2703	Town of Charleston
2706	Town of Minden
2707	Town of Mohawk
2708	Town of Palatine
2709	Town of Root
2702	Town of Canajoharie
2714	Village of Fort Plain
2713	Village of Canajoharie
2705	Town of Glen
2715	Village of Fultonville

REMARKS:

N/A=handled by DCO

Five outside runs, chain link doors, bottom pipe has an 8' area of rust that needs wire brushing and repainting. One frame the bottom joint is loose and needs an L for support. Currently the dogs are mostly in the play yards or indoor kennel with air conditioning and not in the outdoor runs adjoining the kennel. Expect that the minor repainting etc. can be accomplished before the dogs will be utilizing the outdoor runs consistently. The indoor run doors have been completely replaced. Re inspect in 3 months.

REPRESENTATIVE PRESENT FOR INSPECTION:
TITLE: **Kennel Assistant**

Marissa Christman

REVIEWED BY: **Inspector #: 833**
REVIEWED DATE: **07/12/2021**