NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Satisfactory365** Purpose: **Inspection**

DATE/TOA: **7/1/21 2:30 pm**

HUMANE SOCIETY OF WALDEN
2489 ALBANY POST ROAD
WALDEN NY 12586

Inspector #: **67**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	Yes
Shelter has many exterior runs in need of repair but they are not in use.	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3304	Town of Crawford
3312	Town of Montgomery
3303	Town of Cornwall
5117	Town of Shawangunk

REMARKS:

'Front side" of the building exterior runs needing repair from entry are- #3 has crack in concrete, #5 has door support fully rusted through, #8 has concrete erosion that needs repair, #9 has broken rusted post. Exterior runs on the "back side" of the building needing repair are - #1 has broken support, #3,#4,#5,#6,#8,#9,#10 have rusted door support or rusted support columns to the point of rusted completely through where dog could sustain injury.

Shelter staff states runs in need of repair are not being used. Shelter utilizes outdoor exercise pens for dogs housed in these interior kennels.

REPRESENTATIVE PRESENT FOR INSPECTION: **Marissa Owen**
TITLE: **shelter manager**

REVIEWED BY: **Inspector #: 18**
REVIEWED DATE: **07/12/2021**