

## MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**Purpose: **Inspection**DATE/TOA: **3/8/22 11:00 am**

**WOODBURY ANIMAL SHELTER**  
**71 SHUNEMUNK ROAD**  
**Highland Mills NY 10930**

Inspector #: **847**


---

These are the findings of an inspection of your facility on the date(s) indicated above:

---

- |   |     |
|---|-----|
| <b>1. Shelter is structurally sound</b>   | Yes |
| <b>2. Housing area and equipment is sanitized regularly</b>   | Yes |
| <b>3. Repairs are done when necessary</b>   | No  |
| <i>Kennels # 1 and 3 have surfaces with compromised disinfectable surfaces. Kennels #4, 5, 6, 7, and 8 all have deep cracks in the floor surfaces which cause a safety issue and causes a cavity for bacteria and diseases to harbor. Dividers outside kennels 6, 7, and 8 have rusted poles with jagged edges causing a a safety concern as well a nondisinfected surface.</i> |     |
| <b>4. Dogs are handled safely</b>   | Yes |
| <b>5. Adequate space is available for all dogs</b>  | No  |
| <i>Only one kennel is approved for used.</i>  |     |
| <b>6. Light is sufficient for observation</b>   | Yes |
| <b>7. Ventilation is adequate</b>   | Yes |
| <b>8. Drainage is adequate</b>  | Yes |
| <b>9. Temperature extremes are avoided</b>  | Yes |
| <b>10. Clean food and water is available and in ample amount</b>  | Yes |
| <b>11. Veterinary care is provided when necessary</b>   | Yes |
| <b>12. Dogs are euthanized humanely, by authorized personnel</b>  | Yes |
| <b>13. Complete intake and disposition records are maintained for all seized dogs</b>   | Yes |
| <b>14. Dogs transferred for purposes of adoption in compliance with Article 7</b>   | Yes |
| <b>15. Redemption period is observed before adoption, euthanasia or transfer</b>  | Yes |
| <b>16. Owners of identified dogs are properly notified</b>  | Yes |
| <b>17. Redeemed dogs are licensed before release</b>  | Yes |
| <b>18. Proper impoundment fees paid before dogs are released</b>  | Yes |
| <b>19. Written contract or lease with municipality</b>  | Yes |

---

Town - City - Village Information for Inspection:

---

<b>TCV CODE</b>	<b>TCV NAME</b>
3311	Town of Monroe

REMARKS:

REPRESENTATIVE PRESENT FOR INSPECTION: **Pam Gambuti**  
TITLE: **DCO**

REVIEWED BY: **Inspector #: 67**  
REVIEWED DATE: **03/10/2022**