NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 5/4/22 1:15 pm

ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER 2976 COUNTY RD 48 CANANDAIGUA NY 14424 Inspector #: 72

1. Shelter is structurally sound	Yes

These are the findings of an inspection of your facility on the date(s) indicated above:

c	
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	No
See remarks.	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV NAME
Town of East Bloomfield
Town of Farmington
Town of Bristol
Town of Canadice
Town of Canandaigua
Town of Gorham
Town of Hopewell
Town of Manchester
Town of Naples
Town of Phelps
Town of Richmond
Town of Seneca
Town of South Bristol
Town of Victor
Town of West Bloomfield
City of Canandaigua
City of Geneva
Town of Geneva

REMARKS:

The floor drains in every kennel are completely rusted. The guillotine doors in every kennel have rust on them and need maintenance. The chains/metal pulls used to open the guillotine doors are also rusted to varying degrees and need maintenance.

REPRESENTATIVE PRESENT FOR INSPECTION:

TITLE: Shelter Coordinator

Erika Murphy

REVIEWED BY: Inspector #: 64
REVIEWED DATE: 05/09/2022