NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS
DIVISION OF ANIMAL INDUSTRY
10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30** Purpose: **Inspection**

DATE/TOA: **7/14/22 10:00 am**

ONTARIO COUNTY HUMANE SOCIETY INC
HAPPY TAILS ANIMAL SHELTER
2976 COUNTY RD 48
CANANDAIGUA NY 14424

Inspector #: **72**
Inspector #: **075**

These are the findings of an inspection of your facility on the date(s) indicated above:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	Yes
3. Repairs are done when necessary	No
See Remarks	
4. Dogs are handled safely	Yes
5. Adequate space is available for all dogs	Yes
6. Light is sufficient for observation	Yes
7. Ventilation is adequate	Yes
8. Drainage is adequate	Yes
9. Temperature extremes are avoided	Yes
10. Clean food and water is available and in ample amount	Yes
11. Veterinary care is provided when necessary	Yes
12. Dogs are euthanized humanely, by authorized personnel	Yes
13. Complete intake and disposition records are maintained for all seized dogs	Yes
14. Dogs transferred for purposes of adoption in compliance with Article 7	Yes
15. Redemption period is observed before adoption, euthanasia or transfer	Yes
16. Owners of identified dogs are properly notified	Yes
17. Redeemed dogs are licensed before release	Yes
18. Proper impoundment fees paid before dogs are released	Yes
19. Written contract or lease with municipality	Yes

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

REMARKS:

The floor drains in every kennel are completely rusted. The guillotine doors in every kennel have rust on them and need maintenance. The chains/metal pulls used to open the guillotine doors are also rusted to varying degrees and need maintenance. The grout in kennels #8, #11 & #16 need to be repaired. The cinder blocks in the kennel area are not sealed and porous. The grout repairs made in recent months are not adhering to the cinder block. It is recommended that porous surfaces be sealed to prevent water damage and allow for thorough sanitation. It would also allow for a quicker drying time and alleviate extended damp conditions in the housing area.

Also present for the inspection representing Ontario County:
Jesse Gotham, Buildings & Grounds Project Manager
Paul Jansen, Buildings & Grounds Maintenance Mechanic

REPRESENTATIVE PRESENT FOR INSPECTION: **William Martin**
TITLE: **Shelter Director**

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **07/20/2022**