

## MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**

Purpose: **Inspection**

DATE/TOA: **10/27/22 11:00 am**

**ONTARIO COUNTY HUMANE SOCIETY INC  
 HAPPY TAILS ANIMAL SHELTER  
 2976 COUNTY RD 48  
 CANANDAIGUA NY 14424**

Inspector #: **72**

---

These are the findings of an inspection of your facility on the date(s) indicated above:

---

- |   |     |
|---|-----|
| <b>1. Shelter is structurally sound</b>   | Yes |
| <b>2. Housing area and equipment is sanitized regularly</b>                           | Yes |
| <b>3. Repairs are done when necessary</b>   | No  |
| <i>See remarks</i>  |     |
| <b>4. Dogs are handled safely</b>   | Yes |
| <b>5. Adequate space is available for all dogs</b>                                    | Yes |
| <b>6. Light is sufficient for observation</b>   | Yes |
| <b>7. Ventilation is adequate</b>   | Yes |
| <b>8. Drainage is adequate</b>  | Yes |
| <b>9. Temperature extremes are avoided</b>  | Yes |
| <b>10. Clean food and water is available and in ample amount</b>                      | Yes |
| <b>11. Veterinary care is provided when necessary</b>                                 | Yes |
| <b>12. Dogs are euthanized humanely, by authorized personnel</b>                      | Yes |
| <b>13. Complete intake and disposition records are maintained for all seized dogs</b> | Yes |
| <b>14. Dogs transferred for purposes of adoption in compliance with Article 7</b>     | Yes |
| <b>15. Redemption period is observed before adoption, euthanasia or transfer</b>      | Yes |
| <b>16. Owners of identified dogs are properly notified</b>                            | Yes |
| <b>17. Redeemed dogs are licensed before release</b>                                  | Yes |
| <b>18. Proper impoundment fees paid before dogs are released</b>                      | Yes |
| <b>19. Written contract or lease with municipality</b>                                | Yes |

---

 Town - City - Village Information for Inspection:
 

---

<b>TCV CODE</b>	<b>TCV NAME</b>
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

## REMARKS:

**Also present for the inspection:****Erika Murphy, Shelter Coordinator****Paul Jansen, Senior Maintenance Mechanic, Ontario County Buildings & Grounds**

The floor drains in every kennel are completely rusted. Mr. Jansen reviewed the various options researched to correct the issue moving forward. A tentative solution has been decided upon to correct the issue, as well as, a long-term maintenance schedule to maintain the repair.

The guillotine doors in every kennel have rust one them and need maintenance, except one. Kennel #24 has a custom galvanize stainless steel guillotine door and new tracking for the door installed. Mr. Jansen stated these will be installed in all of the kennels moving forward.

The cinder blocks in the kennel area are not sealed and porous. Grout repairs have been done to correct the missing grout present at the previous inspection. It is recommended that porous surfaces be sealed to prevent further water damage and allow for thorough sanitation. It would also allow for a quicker drying time and alleviate extended damp conditions in the housing area. Mr. Jansen discussed the options that are currently being researched for sealing the cinder blocks.

REPRESENTATIVE PRESENT FOR INSPECTION: **William Martin**  
 TITLE: **Shelter Director**

REVIEWED BY: **Inspector #: 64**  
 REVIEWED DATE: **10/31/2022**