## NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS **DIVISION OF ANIMAL INDUSTRY** 10B AIRLINE DRIVE, ALBANY, NY 12235

## **MUNICIPAL SHELTER INSPECTION REPORT - DL-90**

These are the findings of an inspection of your facility on the date(s) indicated above:

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 3/14/23 1:15 pm

72

Yes

**ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER** 2976 COUNTY RD 48 **CANANDAIGUA NY 14424** 

4. Dogs are handled safely

Inspector #:

1. Shelter is structurally sound	Yes
2. Housing area and equipment is sanitized regularly	
3. Repairs are done when necessary	
See remarks.	

5. Adequate space is available for all dogs Yes 6. Light is sufficient for observation Yes 7. Ventilation is adequate Yes 8. Drainage is adequate Yes 9. Temperature extremes are avoided Yes 10. Clean food and water is available and in ample amount

Yes 11. Veterinary care is provided when necessary Yes 12. Dogs are euthanized humanely, by authorized personnel Yes 13. Complete intake and disposition records are maintained for all seized dogs Yes 14. Dogs transferred for purposes of adoption in compliance with Article 7 Yes 15. Redemption period is observed before adoption, euthanasia or transfer Yes 16. Owners of identified dogs are properly notified Yes 17. Redeemed dogs are licensed before release Yes 18. Proper impoundment fees paid before dogs are released Yes 19. Written contract or lease with municipality Yes DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

TCV CODE	TCV NAME
3204	Town of East Bloomfield
3205	Town of Farmington
3201	Town of Bristol
3202	Town of Canadice
3203	Town of Canandaigua
3207	Town of Gorham
3208	Town of Hopewell
3209	Town of Manchester
3210	Town of Naples
3211	Town of Phelps
3212	Town of Richmond
3213	Town of Seneca
3214	Town of South Bristol
3215	Town of Victor
3216	Town of West Bloomfield
3217	City of Canandaigua
3218	City of Geneva
3206	Town of Geneva

## **REMARKS:**

## Repairs:

TITLE: Shelter Director

The floor drains in every kennel are completely rusted: no change since last inspection.

Multiple kennels have guillotine doors with rust on them and need maintenance: One kennel door has been replaced since last inspection.

The cinder blocks in the kennel area are not sealed and porous. It is recommended that porous surfaces be sealed to prevent further water damage and allow for thorough sanitation. It would also allow for quicker drying times to alleviate extended damp conditions in the housing areas.

REPRESENTATIVE PRESENT FOR INSPECTION:

**William Martin** 

REVIEWED BY: Inspector #: 64
REVIEWED DATE: 03/21/2023