NEW YORK STATE DEPARTMENT OF AGRICULTURE AND MARKETS DIVISION OF ANIMAL INDUSTRY 10B AIRLINE DRIVE, ALBANY, NY 12235

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

These are the findings of an inspection of your facility on the date(s) indicated above:

Rating: Unsatisfactory30 Purpose: Inspection

DATE/TOA: 5/19/23 11:45 am

Yes

ONTARIO COUNTY HUMANE SOCIETY INC HAPPY TAILS ANIMAL SHELTER 2976 COUNTY RD 48 CANANDAIGUA NY 14424

19. Written contract or lease with municipality

Inspector #: 72

| 1. Shelter is structurally sound | Yes | |
|--|-----|--|
| 2. Housing area and equipment is sanitized regularly | | |
| 3. Repairs are done when necessary | | |
| See remarks. | | |
| 4. Dogs are handled safely | Yes | |
| 5. Adequate space is available for all dogs | Yes | |
| 6. Light is sufficient for observation | Yes | |
| 7. Ventilation is adequate | Yes | |
| 8. Drainage is adequate | Yes | |
| 9. Temperature extremes are avoided | Yes | |
| 10. Clean food and water is available and in ample amount | | |
| 11. Veterinary care is provided when necessary | | |
| 12. Dogs are euthanized humanely, by authorized personnel | Yes | |
| 13. Complete intake and disposition records are maintained for all seized dogs | Yes | |
| 14. Dogs transferred for purposes of adoption in compliance with Article 7 | Yes | |
| 15. Redemption period is observed before adoption, euthanasia or transfer | Yes | |
| 16. Owners of identified dogs are properly notified | Yes | |
| 17. Redeemed dogs are licensed before release | Yes | |
| 18. Proper impoundment fees paid before dogs are released | Yes | |

DL-90 Page 2 of 2

Town - City - Village Information for Inspection:

| TCV CODE | TCV NAME |
|----------|-------------------------|
| 3204 | Town of East Bloomfield |
| 3205 | Town of Farmington |
| 3201 | Town of Bristol |
| 3202 | Town of Canadice |
| 3203 | Town of Canandaigua |
| 3207 | Town of Gorham |
| 3208 | Town of Hopewell |
| 3209 | Town of Manchester |
| 3210 | Town of Naples |
| 3211 | Town of Phelps |
| 3212 | Town of Richmond |
| 3213 | Town of Seneca |
| 3214 | Town of South Bristol |
| 3215 | Town of Victor |
| 3216 | Town of West Bloomfield |
| 3217 | City of Canandaigua |
| 3218 | City of Geneva |
| 3206 | Town of Geneva |
| | |

REMARKS:

Repairs:

The floor drains in kennels are completely rusted: Drains in kennels 14, 16, 33, 34, 35, 36 & 37 have been sand-blasted and sealed since last inspection.

Multiple kennels have guillotine doors with rust on them and need maintenance.

The cinder blocks in the kennel area are not sealed and porous. It is recommended that porous surfaces be sealed to prevent further water damage and allow for thorough sanitation. It would also allow for quicker drying times to alleviate extended damp conditions in the housing areas. One kennel floor has been sealed with three different materials to test for efficacy since the last inspection.

REPRESENTATIVE PRESENT FOR INSPECTION: Erika Murphy REVIEWED BY: Inspector #: 64
TITLE: Shelter Coordinator REVIEWED DATE: 05/23/2023