

MUNICIPAL SHELTER INSPECTION REPORT - DL-90

Rating: **Unsatisfactory30**

Purpose: **Inspection**

DATE/TOA: **6/13/23 11:30 am**

**PORTVILLE DOG SHELTER
1102 OLEAN-PORTVILLE ROAD
PORTVILLE NY 14770**

Inspector #: **074**

These are the findings of an inspection of your facility on the date(s) indicated above:

- 1. Shelter is structurally sound Yes
- 2. Housing area and equipment is sanitized regularly No
Rust on metal walls/doors and posts can not be properly cleaned and sanitized. Old dog food and bedding still remains on floor of right-most kennel from last use.
- 3. Repairs are done when necessary No
Metal trim on dividing wall of right-most kennel is pried away from wire mesh, creating a sharp edge.
- 4. Dogs are handled safely Yes
- 5. Adequate space is available for all dogs Yes
- 6. Light is sufficient for observation Yes
- 7. Ventilation is adequate Yes
- 8. Drainage is adequate Yes
- 9. Temperature extremes are avoided Yes
- 10. Clean food and water is available and in ample amount Yes
- 11. Veterinary care is provided when necessary Yes
- 12. Dogs are euthanized humanely, by authorized personnel Yes
- 13. Complete intake and disposition records are maintained for all seized dogs Yes
- 14. Dogs transferred for purposes of adoption in compliance with Article 7 Yes
- 15. Redemption period is observed before adoption, euthanasia or transfer Yes
- 16. Owners of identified dogs are properly notified Yes
- 17. Redeemed dogs are licensed before release Yes
- 18. Proper impoundment fees paid before dogs are released Yes
- 19. Written contract or lease with municipality Not Applicable

Town - City - Village Information for Inspection:

TCV CODE TCV NAME

0427 Town of Portville

REMARKS:

REPRESENTATIVE PRESENT FOR INSPECTION: **Yvonne Rogers**
TITLE: **Town Clerk**

REVIEWED BY: **Inspector #: 64**
REVIEWED DATE: **06/14/2023**